

Quality and Utility Assessment of Completed EPA's

District: ARWAAL Project Title: ARWAAL -WDC- 1/2021-22

Block: BANSI Panchayat: CHAMANDI Village: CHAMANDI Beneficiary Name: SHIV SHANKAR SAW

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17760	Structure: HAND PUMP	25.121037 84.77003	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कमिथल का चक्रन एवं गुणवत्ता ठीक है, जो कि ग्रामिणों के अनुसार
हैंडपंप का उपयोग किया जाता है, स्थल पर पर डिस्पले बोर्ड
प्राप्त गाम, लेकिन उसका स्थिति ठीक नहीं है। डिस्पले बोर्ड में
जहाँ नाम लिखा होता है, उसे किसी ने चेंद कर दिया है।

Visit Date:- 11/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar