

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: Pmksy 2.0 -WDC- III/2021-22

Block: Nabinagar , Panchayat: Basdiha , Village: Munga , Beneficiary Name: Asmrani Mishra

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18937	Structure:							
	Chabutra	24.542739 84.111356	100 %	100 %	100 %	100 %	100 %	100

Remark (Overall Quality & Utility of Structure):

कार्यस्थल एवं structure की गुणवत्ता अच्छी है, लोगो द्वारा सामाजिक कार्य हेतु उपयोग में है। structure के पास display board लगा हुआ है।

Visit Date :- 12.10.23

Name :- Shishupal

Sign :- Shishupal