

Quality and Utility Assessment of Completed EPA's

District: Aurangabad , Project Title: PmkSY 2.0 -WDC-III/2021-22

Block: Nabinagar , Panchayat: khajuri Pandu , Village: Mehandi Bigha , Beneficiary Name: Jitendra mehta

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18929	Structure: Hand tubewell with Soak Pit	24.50932 84.11067	100%	100%	100%	40%	40%	76

Remark (Overall Quality & Utility of Structure):

कार्यस्थल का यथन अच्छा है, स्थल पर चापाकल मौजूद नहीं है। लोगों के अनुसार चापाकल खराब होने के कारण लम्बे समय से उपयोग में नहीं है और ना ही कोई Display Board पाया गया।

Visit date:- 13.10.23

Name:- Shishupal

Sign:- Shishupal