

Quality and Utility Assessment of Completed EPA's

District: ARWAH Project Title: ARWAH -WDC- 1 /2021-22

Block: BANSHI Panchayat: KHARASIN Village: AKROUNJA Beneficiary Name: MANOJ KUMAR

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17762	Structure: Renovation of well	25.101548 84.698241	60%.	100%.	100%.	100%.	40%.	80%.

Remark (Overall Quality & Utility of Structure):

कम स्थल का चयन ठीक नहीं है, लेकिन गुणवत्ता अच्छा है।
पंप से पता चलता है कुआँ का कोई उपयोग नहीं हो रहा है।
स्थल पर डिस्फें कोई कामा गम /

Visit Date:- 08/12/23

Name:- NIRAJ KUMAR

Signature:- Manoj Kumar