

### Quality and Utility Assessment of Completed EPA's

District: BANKA Project Title: BANKA -WDC-III /2021-22

Block: Chandan Panchayat: Chandan Village: Chandan Beneficiary Name: Suresh Pandey

| Work ID | Name/ description of activity       | Latitude & Longitude   | Work Identification<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Site Identification<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Specification<br>Followed<br>(Totally 100%,<br>Mostly 80%,<br>Average 60%,<br>Poor 40%) | Physical Appearance<br>of Structure<br>(Excellent 100%,<br>good 80%,<br>average 60%,<br>poor 40%) | Utility of Structure<br>(In full use 100%,<br>partially used 80%,<br>Yet to be used 70%,<br>Occasionally used 60%,<br>Not used/rarely used 40%) | Average<br>Score |
|---------|-------------------------------------|------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| 1       | 2                                   | 3                      | 4                                                                                 | 5                                                                                 | 6                                                                                       | 7                                                                                                 | 8                                                                                                                                               | 9                |
| 18840   | Structure:<br>Renovation of<br>Well | 24.622174<br>86.672099 | 100%                                                                              | 100%                                                                              | 100%                                                                                    | 100%                                                                                              | 100%                                                                                                                                            | 100%             |

**Remark** (Overall Quality & Utility of Structure):

कार्पस-थर का समय एवं कार्य की गुणवत्ता अच्छी है।  
जो कि ग्रामिणों द्वारा कुँडा का उपयोग किया जा रहा है,  
कुँडा पर चलना विचरों से भी डर था, गया।

Visit Date:- 12/12/23

Name:- Brindaban Mahato

Signature:- Brindaban