

Quality and Utility Assessment of Completed EPA's

District: ARWAL Project Title: ARWAL -WDC- 1 /2021-22

Block: BANSHI Panchayat: SONBHODRA Village: MOULAPUR Beneficiary Name: VINDESHWARI SHARMA

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17766	Structure: Renovation of Well	25.104757 84.714835	100%.	100%.	100%.	100%.	100%.	100%.

Remark (Overall Quality & Utility of Structure):

कमल के चमक एवं गुणवत्ता थी है, जो कि वसतिगो की सुविधा
कुओं के उपयोग के लिए के लिए किया जाता है, कतः
महर्षि लाभप्रद है, स्थल पर पर डिप्लोमा बर्ड पाठ्य गम /

Visit Date:- 09/12/23

Name:- ADIRAJ KUMAR

Signature:- Adiraj Kumar