

# Quality and Utility Assessment of Completed EPA's

District: Baghal Pur Project Title: Baghal Pur -WDC-1 /2021-22

Block: Kachalgaon Panchayat: Ramzanipur Village: DEORI Beneficiary Name: Ramanant Ranjan

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18645	Structure: Chabutra	25°18'14"N 87°19'36"E	100 %	100 %	100 %	100 %	100 %	100 %

Remark (Overall Quality & Utility of Structure):

कार्य स्थल एक कार्य की गुणवत्ता सीक हो जा- कि- ग्रामीणों द्वारा  
यसुरा का उपयोग मजबूत किया गया- खाने-पाने- सामग्री मजबूत  
मजबूत- सरती सुरक्षित के- उपयोग- में लेने है-  
योजना का कार्य लगा हुआ- है-

Visit Date:- 14-3-2024

Name:- Keshal Kumar DFO

Signature:- Keshal Kumar DFO