

### Quality and Utility Assessment of Completed EPA's

District: ARWAH Project Title: ARWAH -WDC- I /2021-22

Block: BANSHI Panchayat: MALI Village: MALI Beneficiary Name: RANJEET RIAK

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17758	Structure: HANDPUMP	25.126728 84.704817	100%	100%	100%	100%	100%	100%

**Remark** (Overall Quality & Utility of Structure):

कर्मस्थल का चमक एवं कर्म की गुणवत्ता शीक है, जो कि ग्रामिणों एवं शस्ते से आते-जाते लोगों के द्वारा हैंडपम्प का उपयोग होता है, ये कर्म लोगों के लिए लाभप्रद है, स्थल पर पर डिप्लेस कोई भी काम नमा ।

Visit Date:- 06/12/23

Name:- ADRAJKUMAR

Signature:- Nishu Kumar