

Quality and Utility Assessment of Completed EPA's

District: ARWAL Project Title: ARWAL -WDC-I /2021-22

Block: BANSAI Panchayat: KHARASIN Village: AKROUNJA Beneficiary Name: HIMANSU KUMAR

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17767	Structure: Removation of well	25.103608 84.700167	100%	100%	100%	100%	60%	92%
Remark (Overall Quality & Utility of Structure): <p>कर्म स्थल का चमक एवं कर्म की गुणवत्ता हीक हैं। जो कि ग्रामियों के द्वारा पूजा-पाठ के समय ही उपयोग के लाया जाता है। प्लॉट के समय पास वाला कि कुआँ का side का स्थान देता हुआ है, स्थल पर पर डिम्पल कीड काम गमा।</p>								
Visit Date:- 08/12/23			Name:- NIDRAJ KUMAR			Signature:- Nidraj Kumar		