

Quality and Utility Assessment of Completed EPA's

District: ARUNACHAL Project Title: ARUNACHAL -WDC-1/2021-22

Block: BANSHI Panchayat: SHARARTIPA Village: MIYA BIGHA Beneficiary Name: GUDDO RAJBANSHI

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17769	Structure: HAND PUMP	25.133485 84.66709	100%	100%	100%	100%	100%	100%

Remark (Overall Quality & Utility of Structure):

कमरे में का चमक एवं गुणवत्ता दी गई है, मशीनों के अनुसार
हैंडपंप का उपयोग किया जाता है, यह कम मशीनों के लिए
लाभदाक है, स्थल पर डिस्पेंस लॉर्ड पाया गया।

Visit Date:- 05/12/23

Name:- MIRAJ KUMAR

Signature:- Miraj Kumar