

Quality and Utility Assessment of Completed EPA's

District: ARWAL Project Title: ARWAL -WDC- 2 /2021-22

Block: BANSHI Panchayat: KEYAL Village: KEYAL Beneficiary Name: RANJEET KUMAR

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
17770	Structure: HAND PUMP	25.113778	100%	100%	100%	100%	100%	100%
		84.630189						

Remark (Overall Quality & Utility of Structure):

कर्मचाल को चमक एवं गुणवत्ता दी गई है; जो कि स्थानियों की अनुमति
हैंडपंप का उपयोग किया जाता है, कता यह काम लोअप्रद काम है।
स्थल पर पर बिस्फले कीटि नहीं पाया गया।

Visit Date:- 09/12/23

Name:- NIRAJ KUMAR

Signature:- Niraj Kumar