

Quality and Utility Assessment of Completed EPA's

District: Aurangabad, Project Title: PmkSY 2.0 -WDC- II/2021-22

Block: Deo, Panchayat: Bedhna, Village: Barheta, Beneficiary Name: Vishunath mahto

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60%, Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60%, Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
5964	Structure: Hand Tube well with soak pit	24.593062	100%	100%	100%	100%	100%	100
		84.426505						

Remark (Overall Quality & Utility of Structure):

Structure की जोखता अच्छी है, सामग्री द्वारा उपयोग किया जा रहा है।
Display board लगा हुआ पाया गया।

Visit Date: - 01-06-2024

Name: - Shishupal

Signature: - Shishupal