

### Quality and Utility Assessment of Completed EPA's

District: Aurangabad, Project Title: Pmksy 2.0 -WDC- II/2021-22

Block: Deo

,Panchayat: Bedhna

,Village: Barheta

,Beneficiary Name: Surendra Bartha

Work ID	Name/ description of activity	Latitude & Longitude	Work Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Site Identification (Excellent 100%, good 80%, average 60%, poor 40%)	Specification Followed (Totally 100%, Mostly 80%, Average 60% Poor 40%)	Physical Appearance of Structure (Excellent 100%, good 80%, average 60%, poor 40%)	Utility of Structure (In full use 100%, partially used 80%, Yet to be used 70%, Occasionally used 60% Not used/rarely used 40%)	Average Score
1	2	3	4	5	6	7	8	9
18963	Structure: Hand tubewell with soak pit	24.590671 84.428243	100 %	100 %	100 %	100 %	100 %	100

**Remark** (Overall Quality & Utility of Structure):

Structure की गुणवत्ता अच्छी है, लाभार्थी द्वारा उपयोग में है, structure के पास display board लगा हुआ पाया गया।

visit date: - 29.09.23

Name: - Shishupal

Sign: - Shishupal